ENGINEERING CHANGE NOTICE

ECN #: 266		
Created By:	Checked By: PF	
Approved By	Approved By: (management if req'd) N/A	
,	Approved By:	

RELEASING THE FOLLOWING DILAMINGS REQUIRED TO MANUFACTURE D407-663-011:

REV. A MOUNTING PLATE D2954 DZ457 REV. A MOUNTING PLATE

DZ952 ROV. A LID BASE rev.A D2948

NOV. A SPACER D2953

D2955 REV. A . ASSEMBLY REV. A LABEL D2961

Notification/Acceptance	Affected ✓	Authorization		
QA	V			
Production	V	0.00		
Planning	V	P00Z-399		
Marketing	N/A			

Engineering Actions	Yes	No	Responsible	To happen by:	Complete
Update Blue File		V			
Update Pink File		>			
Update D-Part Master Binder	V		PS	00.02,21	00.02.21 05
Update Grey Project Binder	V		DS	00.02.04	00.02.04 RF
Update DEO Binder					
Update Master Document List					
Update Drawing Approval Record		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			
Update Change Record form		V			
Move Electornic File	·/		DS	00.02.21	00.0221 05
Notify TCA of Change		\			
Notify FAA of Change		'			<u> </u>

Notes:

- CREATE IPP'S FOR ABOVE PAPOTS
- DIVES HAVE BEEN RELEASED TO PRODUCTION FOR PROTOTYPE MANUFACTURE FOR TESTING. PLEASE KEEP QUANTIES TO A MINIMUM HATL THE PROTOTIFE HAS BEEN APPROVED AND DOT APPROVED HAS BEEN RECEIVED.
- ORDER ,75 x.75 x.049 WALL SS TUBING + .75 x.75 x.060 6061-76 TUBING
- D2953 SPACER MAT. IS SAME AS D2649 FOR 206 SKIDTUBES
- DO WE HAVE 5052-H32/H34 .032 THICK IN STOCK?
- DZ957 PROBERCY REQUIRES HAMS PROGRAM
- Digst PROBLEM REQUES LASER CUTING